



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	268	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	4	Setup No:	3	Priority CCTV:	

House Number	6950	Street Prefix:		Street Name:	Reisterstown	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 463

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0463.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 14
Setup No. 3

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/09	Start Time: 1305
Crew: T2	Street Location: Reisterstown Rd		
US MH: 1520911	DS MH: 1520910	Number of Segments: 3	Test Length: 760'
Plugged US: <input checked="" type="radio"/> N	Plugged DS: <input checked="" type="radio"/> N	# of Blowers: 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="radio"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 268

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\268.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	268	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	5	Setup No:	3	Priority CCTV:	

House Number	6944	Street Prefix:		Street Name:	Reisterstown	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above grade						

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 464

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0464.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 14
Setup No. 3

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/09	Start Time: 1305
Crew: T2	Street Location: Reisterstown Rd		
US MH: 1520911	DS MH: 1520910	Number of Segments: 3	Test Length: 760'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 268

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\268.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	268	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	6	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
4110		Fallstaff	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	4		

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 466

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0466.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 14
Setup No. 3

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/09	Start Time: 1305
Crew: T2	Street Location: Reisterstown Rd		
US MH: 1520911	DS MH: 1520910	Number of Segments: 3	Test Length: 760'
Plugged US: <input checked="" type="radio"/> N	Plugged DS: <input checked="" type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="radio"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 268

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\268.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	268	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	7	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
4120		Fallstaff	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments: Above grade

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 465

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0465.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 14
Setup No. 3

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/09	Start Time: 1305
Crew: T2	Street Location: Reisterstown Rd		
US MH: 1520911	DS MH: 1520910	Number of Segments: 3	Test Length: 760'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: ① 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

← Reisterstown Rd →

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 268

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\268.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
4023		Fallstaff	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
---------------------	--------------	------------------	--------------	------------------	---------

Sector:	2=Private	Drainage Area:	0
----------------	-----------	-----------------------	---

Comments: Above Grade

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 467

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0467.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.

SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

Page 1 of 2
Smoke Set No. 15
Setup No. 4

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls Tg Off Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers 1(2)3	Ground: (Dry) Moderate Wet
Plugs Removed? Y N	Recorder: Bob Blank	Comments: —	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	10	Setup No:	4	Priority CCTV:	

House Number	4001	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 476

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0476.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	11	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6921		Reisterstown	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
---------------------	--------------	------------------	--------------	------------------	---------

Sector:	2=Private	Drainage Area:	0
----------------	-----------	-----------------------	---

Comments: Above Grade

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 477

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0477.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No:

269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	12	Setup No:	4	Priority CCTV:	

House Number	6915	Street Prefix:		Street Name:	Reisterstown	Street Type:	ROAD
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	15				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 478

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0478.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	2	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:		
4023		Fallstaff	ROAD		
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	30		
Comments:					

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 468

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0468.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	3	Setup No:	4	Priority CCTV:	

House Number	4019	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 469

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0469.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	4	Setup No:	4	Priority CCTV:	

House Number	4017	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 470

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0470.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	5	Setup No:	4	Priority CCTV:	

House Number	4013	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	2=Trace		
Sector:	2=Private	Drainage Area:	15				
Comments:							

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 471

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0471.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No:

269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	6	Setup No:	4	Priority CCTV:	

House Number	4015	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	2=Trace		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS




Photo No:
Filename Path:

Image Status: No image name specified.

Photo No: 472

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0472.JPG

Image Status: Image found and displayed.

Photo No:
Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No:

269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	7	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:		
4015		Fallstaff	ROAD		
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	50		
Comments:					

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 473

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0473.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No:

269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	8	Setup No:	4	Priority CCTV:	

House Number	4005	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	50				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 474

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0474.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

269

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No:

269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	269	Date:	10/11/2004	MeterBasin:	
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	9	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
4003		Fallstaff	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		
Comments:	Above Grade				

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 475

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0475.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 4

BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM

269

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1430
Crew: T2	Street Location: Falls 9th Rd		
US MH: 1522229	DS MH: 1520918	Number of Segments: 8	Test Length: 1702'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: Bob Bink	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 10/5/2004 Leader Form

Sketch No: 269

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\269.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	270	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	1	Setup No:	5	Priority CCTV:	

House Number	4026	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 479

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0479.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 5

270

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1610
Crew: T2	Street Location: Falls to FF Rd		
US MH: 1522226	DS MH: 1521315	Number of Segments: 4	Test Length: 1039'
Plugged US: Y <input checked="" type="checkbox"/> N	Plugged DS: Y <input checked="" type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry Moderate Wet
Plugs Removed? Y <input checked="" type="checkbox"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 270

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\270.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	270	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	2	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
4022		Fallstaff	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
---------------------	--------------	------------------	--------------	------------------	---------

Sector:	2=Private	Drainage Area:	0
----------------	-----------	-----------------------	---

Comments: Above Grade

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 480

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0480.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.




SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 5

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**270

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1610
Crew: T2	Street Location: Falls to ff Rd		
US MH: 1522226	DS MH: 1521315	Number of Segments: 4	Test Length: 1039'
Plugged US: Y <input checked="" type="checkbox"/> N	Plugged DS: Y <input checked="" type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry Moderate Wet
Plugs Removed? Y <input checked="" type="checkbox"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



CREW COMMENTS

Last Revised 9/16/2004Leader Form

Sketch No: 270

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\270.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	270	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	4020	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 481

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0481.JPG

Image Status: Image found and displayed.

Photo No:


Filename Path:

Image Status: No image name specified.

SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

		Page 1 of 2	
		Smoke Set No. <u>15</u>	
		Setup No. <u>5</u>	
BUREAU OF WATER AND WASTEWATER SMOKE TEST INSPECTION FORM			
270			
TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1610
Crew: T2	Street Location: Falls Tgff Rd		
US MH: 1522226	DS MH: 1521315	Number of Segments: 4	Test Length: 1039'
Plugged US: Y (N)	Plugged DS: (Y) N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? (Y) N	Recorder: Bob Blank	Comments:	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			
<div style="position: relative;"> <div style="position: absolute; left: -100px; top: 50px;"> ↑ Glensyle Ave. ↓ </div> <div style="position: absolute; left: 0; top: 100px;"> <p>← Reisters town Rd →</p> </div> <div style="position: absolute; left: 100px; top: 100px;"> <p>1521315 186' 171' 1520717 1520489</p> </div> <div style="position: absolute; left: 200px; top: 100px;"> <p>87 x</p> </div> <div style="position: absolute; left: 300px; top: 100px;"> <p>X B1 339'</p> </div> <div style="position: absolute; left: 400px; top: 100px;"> <p>X B2</p> </div> <div style="position: absolute; left: 500px; top: 100px;"> <p>X B3</p> </div> <div style="position: absolute; left: 600px; top: 100px;"> <p>X B4 340'</p> </div> <div style="position: absolute; left: 700px; top: 100px;"> <p>X B5</p> </div> <div style="position: absolute; left: 800px; top: 100px;"> <p>X B6</p> </div> <div style="position: absolute; left: 900px; top: 100px;"> <p>1522226</p> </div> <div style="position: absolute; left: 150px; top: 150px;"> <p>4038</p> </div> <div style="position: absolute; left: 250px; top: 150px;"> <p>4040</p> </div> <div style="position: absolute; left: 350px; top: 150px;"> <p>4042</p> </div> <div style="position: absolute; left: 450px; top: 150px;"> <p>4044</p> </div> <div style="position: absolute; left: 550px; top: 150px;"> <p>4046</p> </div> <div style="position: absolute; left: 650px; top: 150px;"> <p>4048</p> </div> <div style="position: absolute; left: 750px; top: 150px;"> <p>4050</p> </div> <div style="position: absolute; left: 850px; top: 150px;"> <p>4052</p> </div> <div style="position: absolute; left: 950px; top: 150px;"> <p>4054</p> </div> <div style="position: absolute; left: 100px; top: 200px;"> <p>N</p> </div> </div>			
CREW COMMENTS			

Last Revised 9/16/2004

Leader Form

Sketch No: 270

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\270.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	270	Date:	10/11/2004	MeterBasin:	01_WR32
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	4	Setup No:	5	Priority CCTV:	

House Number	4008	Street Prefix:		Street Name:	Fallstaff	Street Type:	ROAD
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	0				
Comments:	Above Grade						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 482

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1011-2004\T-2\PLAYER_B\B_2004_1011Image0482.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 15
Setup No. 5

270

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/11/04	Start Time: 1610
Crew: T2	Street Location: Falls to ff Rd		
US MH: 1522226	DS MH: 1521315	Number of Segments: 4	Test Length: 1039'
Plugged US: Y <input checked="" type="checkbox"/> N	Plugged DS: Y <input checked="" type="checkbox"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="checkbox"/> Dry Moderate Wet
Plugs Removed? Y <input checked="" type="checkbox"/> N	Recorder: Bob Blank	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 270

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\270.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.